

Received from Chief Ship Surveyor.....15 AUG 1962.....

SHIP NAME "WING ON" REPORT SNG. No. 1577

standing Conditions of Class: SUBJECT to shell plates No.1 in 3rd strake below sheerstrake (p & s) (doubled) and rudder post plating between 17/18' draft marks (p & s) being specially examined and dealt with as necessary by the next drydocking, and to leaky shell plate in 3rd strake below sheerstrake in way of A.P. tank (s.s) being specially examined and dealt with as necessary by 6,62.

L. Appendix. (As before or None)

Re of Present Survey: (Afloat and in dry dock)

Repairs to leaky shell plate in way of A.P. tank (s.s) as above.

Recommendation: SUBJECT to shell plates No.1 in 3rd strake below sheerstrake (p & s) (doubled) and rudder post plating between 17/18' draft marks (p & s) being specially examined and dealt with as necessary by the next drydocking, without other conditions.

As Now Subject  
without.



© 2021

Lloyd's Register  
Foundation

010933-010942-0097

the 050 List and a suitable note