

Im. 5.62

Class is subject to

- ① Port centre aux. engine bedplate (Mchlock 7/60) being examined by 5/62 (12 mos limit)
- ② M.E. N^o 1 and 2 cylinder covers (Mchlock 5/61) being 4E examined by 4/62 3.63 (12 mos limit)
- ③ Donley boiler not to be used until DBS is completed

15 AUG 1962

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME "WING ON" REPORT SN9 No. 15773

SRL Item ① The Surveyor reports this item examined and remains efficient and recommends it be re-examined by 5/63. It is submitted this item be removed from the list and a note made in the appendix.

It is submitted that this vessel is eligible to remain as **CLASSED**.

Subject as above re Items ② and ③ but without subject re Item ①

See letter 2/10/62
examined
and
2/10/62

The Surveyor to be advised that where a Mchlock repair has been examined twice over a period of two years and found satisfactory it may be removed from the SR list and a suitable note made in the appendix. In the circumstances an amended interim certificate should be issued.

S.R.L. - Appendix Note

Port centre auxiliary engine bedplate Mchlock repaired.

010933-010942-0098

© 2021 Lloyd's Register Foundation