

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report.....19..... When handed in at Local Office.....19..... Port of.....

No. in Reg. Book. 19090 Survey held at on the Wood, Iron or Steel Date, First Survey S.S. MENTOR Last Survey 19

Tonnage: GROSS 1368 UNDER DK 1199 NET 820 Built at Haarlem By whom N.V. Werf Conrad When 1918 Owners Cia. Mar Mentor S.A. Owners' Address ✓ Managers ✓ Port belonging to Panama

Surveyed Afloat or in Dry Dock? ✓ Name of Dock..... Destined Voyage ✓

Cell D/Bor D/Ba..... feet; uE & B..... feet; f..... feet; total capacity..... tons. FPT..... tons; APT..... tons; MT..... feet..... tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER * for Special Survey, Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>100A1</u>	<u>LMC 4-48</u>
<u>12-50</u>	<u>BS 6-51</u>
<u>S.S. Ply 2nd No 311/41 JS4-49 CL</u>	
<u>S.S. Bry 4-48</u>	
<u>Cargo battens not fitted</u>	

Last Report, No. 57542 Port Leff

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ... ..								
Removed and Fairred or Repaired								
Fairred or Repaired in place ...								

PRESENT CONDITION OF THE		Copper, or Y.M. (State if on Felt.)	
Decks	Bulkheads	When fitted, Month	Year
Caulking of Decks	Ceiling	Boats	
Coamings	Cement or Asphalt	Masts, Yards, &c.	
Beams & Fastenings	Rudder	Condition, how ascertained (State if wedges removed.)	
Outside Plating	Steering gear and its connections	Equipment letter	
" " in way of sidelights	Windlass	Ancora, No. of	
Frames	Have pumps been examined and found efficient?	Cables (State if now ranged)	
Reverse Frames	Have Sluice Valves been examined and found efficient?	" length mean diamr. (on board.)	
Longitudinals	Have Watertight Doors been examined and found efficient?	" Rule length size	
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Chain Locker	
Floors	Air and Sounding Pipes	Hawsers & Werps	
Keelsons	Doubling Plates under Sounding Pipes	Standing and Running Rigging	
Stringers		Sails	
Inner Bottom Plating			
Have the Tanks been examined internally?			
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c. : State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of as No. 1-38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	10
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	10

Committee's Minute..... Character Assigned.....

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

20th, 1920. Transfer In. (MADE AND PRINTED IN ENGLAND.) (The Surveyors are requested not to write on or below the space for Committee's Minutes.)

S 800-146210-28610 010982-01941-0085

Is Certificate required? If so, to be sent to

Surveyor to Lloyd's Register of Shipping. GENERAL COMMITTEE Thursday 6th March, 1920. Lloyd's Register Foundation. decision confirmed.