

The class is subject to the combustion chambers of both boilers  
renewed at the next B.S.

5 E

172 NOV 1948

of Engineer Surveyor..... Received from Chief Engineer Surveyor.....

NAME "TOAS"..... REPORT Cco..... No. 3154.....

the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and  
bringing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points  
stated in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

~~DAMAGE BY WEAR AND TEAR.~~

Temporary repairs have now been effected to the centrifugal  
circulating pump. Damage was caused in an effort to clear the main  
injection valve. The casing of the pump was cracked together with  
the end door. Efficient temporary repairs have been effected to  
the Surveyor recommends that the circulating pump casing be renewed  
at the earliest opportunity.

The low injection valve has now been renewed.

It is submitted the vessel is eligible to remain as classed, with

Record-of-Survey subject as recommended, and as above.



© 2021

11.11.48

Lloyd's Register  
Foundation

010982-010991-0219