

Surveyors.....

Received from Chief Surveyors.....

ME

"FLYING SPITFIRE"

REPORT.....

Gls.

No. 91194

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Survey. Docking: Permanent repairs to ~~When done~~  
damage caused by grounding.


NOTE D.

SUBJECT to sternframe (E.W.3,60) being specially examined at the next drydocking.

It would appear that the plans mentioned in the report were not forwarded with the report, and the Surveyors should be requested to repair this omission.

Checked by  
H. Dept

DBM.  
14.4.68



© 2021

Lloyd's Register  
Foundation

011032-011036-02214