

2 E

29 MAR 1957

Inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

Ship's NAME

ELDAREN

REPORT

memo

No.

3666

L/MC (M) due 2.57 } now held.
 S/S " 3.57 }

and the following repairs carried out (due to):-

Loosening Screwballs drawn and examined

IT IS SUBMITTED the vessel is eligible to remain as classed.

with RECORD of survey + L/MC (M) 2.57. S/S 2.57 as recommended.
 and S 2.57

It is concluded the donkey boiler securing arrangements were examined & the OF burning apparatus was tested at this time but the surveyor should confirm

X 2/4

yes checked 6/4/57 ✓
 22/3/57
 © 2021
 Lloyd's Register Foundation
 011047-011056-0070