

2

10th February, 1956.

2

BILBAO

11864. As recommended.

"QUES DE URQUIJO". 11862. As recommended, except that a notation of sps 12,55 has also been assigned. It is concluded the thickness of shell plate in F strake (port side forward) where drilled (8 mm), is in way of local pitting and not indicative of the general condition of the plate. Two certificates are therefore enclosed herewith, for issue to the Owners if this conclusion is correct, but I shall, however, be glad to receive your confirmation on this point. At the same time you should state the new diameter of the main engine cylinders, in order that this may be recorded in the Register Book.



011071-011078-0114

© 2021

Lloyd's Register
Foundation