

22 FEB 1962

Received from Chief Ship Surveyor.....

NAME "BABINDA" REPORT Syd. No. 34642

ing Conditions of Class: SUBJECT to No.8 keel plate from forward, to side shell plating in way of stringer brackets between frames 53/54 (s.s.), to sheerstrake No.2 in 2nd below sheer (p.s.f) being specially examined and dealt with as necessary also to fore-castle side plating etc. (p.s.) being dealt with as necessary by the Special Survey. ACTION is DEFERRED for completion of the S.S.

Appendix. (As before ~~or None~~)

due: A SPECIAL SURVEY (D) became due 7,61 but postponement until 7,62 was approved 16.11.61.

f Present Survey: (Afloat ~~and in dry dock~~)

Repairs to fractured frames.

Features:

in Certificate in order (Yes-~~No-None~~)

standing: ~~(If any for S.S.)~~

FOR PORTION OF SURVEY HELD:- See List in Ship Reports Dept.

be completed by:

ation:

SUBJECT as above, but ACTION continue to be DEFERRED for completion of the Special Survey.

SUBJECT

IN S.R.L. APPENBIX.

Indents in shell plates A.1 & B.1 (p.s.f) and in fore-castle and bridge side plating etc. (p.s.).

S.S. PART HELD.

W.S. 1.
22.2.62

© 2021



Lloyd's Register Foundation
01110-01119-0095