

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report No. 593 When handed in at Local Office No. 593 Port of

No. in Reg. Book Survey held at Date, First Survey Last Survey

65558 on the Wood, Iron or Steel Barge KADHAMAH

TONNAGE Built at Wellington Quay on Tyne By whom Belands (Successors) Ltd When 1946 MONTH 6

GROSS 309 Owners Kuwait Oil Co Ltd Owners' Address Managers Port belonging to London

NET 309 Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell DBor DBa feet: uE&B feet: j feet: Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT feet tons. Only alterations in the existing records of tanks should be inserted. N.B.—All alterations in the existing records should be underlined.

Last Report, No. 750 Port Bar.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Caulking of Decks	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Coamings	Rudder	Scuppers	Boats
Beams & Fastenings	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	Windlass	Hatches	Condition, how ascertained
Frames	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	length mean diamr.
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
Stringers		" " at other places	Rule length size
Inner Bottom Plating		Stringers, Clamps & Shelves	Chain Locker
Have the Tanks been examined internally?		Salting	Hawsers & Warps
Have the Tanks been tested?		(State if examined)	Standing and Running Rigging
			Sails

General Observations, Opinion as to Class, Recommendation, &c.: State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute FRIDAY 9 JUL 1954

Character Assigned Withdraw class

Surveyor to Lloyd's Register of Shipping. GENERAL COMMITTEE Thursday 29th July 1954 Classing Committee's decision confirmed.