

to Chief Surveyors.....

Received from Chief Surveyors.....

19 MAR 1950

SEL'S NAME BROOMFIELD

REPORT

Liv.

130384

No.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

e of Survey Docking, Equipment & O.F.
Conversion.

When due

NOTED

Subject to defective rivets in bottom and side frames being renewed and indented bottom and side shell plating being specially examined and dealt with as necessary by next Special Survey.

INSERT IN R.B:

Fitted for O.F. 2.50, FP above 150°F.

FREEBOARD DEPT. TO NOTE:

Alteration to No. 2 hatchway on
R.Q.D.

Noted Mr.

24-3-50

© 2021

Lloyd's Register
Foundation

011251-011258-0026

classified, with fresh record of Survey, 2.50 (undocked 7/2/50) and to have the notation
Sub 2.50 FP above 150°F. This is to be noted.