

Inspected by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

VESSEL'S NAME..... "EMPIRE FAUN"..... REPORT..... PIR..... No. 9081.

ES due 8.59. Partly held now.

MBS due 5.60. Partly held now.

Docking. Tailshaft seen.

The Surveyor reports the tailshaft found with a fracture 2" long extending from the forward end of the keyway into the taper but a spare shaft not available. The Surveyor makes no recommendation as regards the foregoing item and it is submitted that the class be made subject to the tailshaft being renewed before this vessel is placed into service.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh records of ES 6.60 and MBS 6.60 when the surveys have been completed subject to the tailshaft being renewed before the vessel is placed into service.

*Note dates of survey  
and date of writing Report*

*R.*  
28.7.61.

NOTE.

In view of the condition of the tailshaft, the Surveyor should be requested to issue an amended Interim Certificate containing the above recommendation that the tailshaft be renewed before the vessel is placed into service.



© 2021

Lloyd's Register  
Foundation