

L.M.C. 7 Screw Shaft Surveys held
Wear & tear repairs effected

It is estimated
cost to ship to port
L.M.C.D. + L.M.C. 5.47
5 2.47

See Com. to. Roll
21-7-47. 11/9/47

HAULER

Chest renewed, bilge pump ram also renewed. M.E. Feed Pump ram renewed. Circulating Pump Chamber lined, bucket and ram renewed. Condenser opened up, examined and a number of tubes renewed. Condenser tested on completion of repairs.

Auxiliary Machinery. General Service pump and Donkey feed pump completely opened up and examined. Repairs of minor nature effected at this time.

Steering engine completely opened up and examined. Minor repairs effected and engine estimated under working conditions on completion of repairs.

Electric engine opened up and examined and found to be in good condition. Dynamo and electrical equipment examined and Megger tested as per rule.

Boiler opened up and examined internally and externally. Manholes, manhole doors and their fastenings examined.

All mountings opened up and examined. Repairs of minor nature effected at this time. The boiler was afterwards examined under steam, and the safety valves adjusted to blow-off at 127 lb pressure per square inch.

On completion of repairs the Main and Auxiliary machinery was tried under working conditions and found to be satisfactory.

G. M. Macdonald.

