

Received from Chief Ship Surveyor

25 APR 1961

SHIPS NAME

"PEGASUS I" ~~8~~ 31

REPORT

LGS

No.2804

EA

Outstanding Conditions of Class:

SUBJECT to forward port bottom plating of "PEGASUS I" being specially examined and dealt with as necessary next drydocking before 4,61.

S.R.L. Appendix. (As before or None)

Nature of Present Survey: ~~Without~~ in dry dock

SPECIAL SURVEY (A) due 4,61.  
Minor repairs.

Recommendation:

SUBMITTED record of DS 3,61 and Notation of SS 3,61 be assigned as recommended, ~~without special conditions~~

*Subject as above re PEGASUS I*

DS 3,61

SS 3,61 Without.

~~IT IS FURTHER SUBMITTED the Surveyors be advised that when this ship was built there were 30 fathoms of 7/8" dia. chain cable, 1 bower anchor and 1 stream anchor on board and be informed it is concluded that this anchor and chain cable equipment is still on board the ship. They should be referred to their Report No.2478 and be informed it is concluded that the deferred repairs contained in that report have been dealt with at this time, but confirmation is desired.~~

Blk (new)

011280-011293-0311

Hydrographic Foundation

*Handwritten signature and date: 25, Apr 61*

example of drydock

records of