





32 Essential Independent Pumps (Identify by position)
33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls
34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?
35 Fresh Water Coolers
36 Lub. Oil Coolers
37 Heaters (state service)
38 Independent Air Compressors, Coolers & Safety Devices
39 Air Receivers & Safety devices—Main
40 Auxiliary
41 Oil Fuel Tanks (Not forming part of hull structure)
42 Evaporators
43 Have Evaporator Safety Valves been tested under steam?
44 Steering Machinery
45 Windlass
46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)

Table with 4 columns: PROPULSION, PORT, STARBOARD, AUXILIARY EQUIPMENT. Rows include Generators, Exciters, Air Coolers, Motors, Control Gear, Cables, etc., Insulation Resistance, Insulating Oil Test, Overspeed Governors, Magnetic Couplings, Air Gap, and various auxiliary equipment like Generators & Governors, Motors, Switchboards & Fittings, etc.

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)
MAIN
AUXILIARY, DONKEY or PRESS
Superheaters
Safety Valves
Mountings, Doors & Fastenings
Safety Valves Adjusted to Sat. Spt.
Boiler Securing Arrangements
Main Economisers
Exhaust Gas Heated Economisers
Steam Heated Steam Generators
Steam Generator Safety Valves Adjusted to
Were Oil Burning System & Remote Controls examined working in accordance with Rules?
Forced Circulating Pumps
Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?
Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)
Main
Auxiliary (over 3 in. bore)
Were Copper Pipes annealed?
Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

REPAIRS.
+ During the electrical survey it was observed that the main cables from switch board aft, through two decks were damaged and outer linings of cable torn and badly patched. This condition has been temporarily repaired, but it is recommended that the cables in question be renewed at the special survey.
+ On examination of the screwshaft a slight flaw was noted at the forward end of keyway. This has now been cut out and the head of the keyway relieved as per previous instructions. The shaft afterword "MAGNET FLUX" tested and found satisfactory. The owners have been requested to present the taper of this shaft for re-examination within the period of twelve months.

LEAVE THIS SPACE BLANK

Survey fees
Damage fee
Expenses
Date when A/c rendered