

4E

Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

22 DEC 1959

OLIVINA.....

REPORT Hul.....

No. 65471.....

MBS due 10.59. Now held.

W & T Repairs

LP crankpin found slack in crankweb.

At Owners request all crankpins and crankjournals
viewed. Shafting alignment checked and machinery trials satisfact-
carried out.

IT IS SUBMITTED this vessel is eligible for the record
59.



Sign

2021

18.12.59.



Lloyd's Register
Foundation

011397-011407-0257