

Rpt. 8

Port Newcastle, N.S.W.

No.

7790

Date of writing Report 5.4.61.

When handed in at Local Office

Received London

Survey held at Newcastle, N.S.W.

No. of Visits 2

First Date 27.3.1961

Last Date 28.3.1961.

DISCLOSED
SECTION

REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

86531

on the Iron or Steel

S.S.

"WYRALLAH"

Built at Copenhagen

By Whom Sun S.B. & D.D. & Co.

When

Owners John Burke Ltd.

Owner's address
(If not already in R.B.)

Managers

Port of Registry Brisbane

Surveyed Afloat or in Drydock Drydock

Name of Dock State Dockyard Floating Dock Date of last examn. in Drydock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 9182

Port

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr.). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report.

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified ft. ins.

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR

Docking Survey.

The vessel was placed in drydock and an examination carried out in accordance with the Rules.

On the examination of the Hull Plates the top edge of plate B2 was found wasted. The top edge of this plate 9" wide and 12 feet long was cropped, renewed and reriveted and hose tested and found satisfactory.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? Yes

Is Classification Certificate required? If so, to be sent to

If so, is the Report sent now, or when will it be sent? Now

Has Interim Certificate been issued? Yes

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this Survey, for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. 1,55".

In my opinion this vessel so far as now seen is in good condition and eligible to remain as now classed and to have record of D.S. 3/61 made now in the supplement to the Register Book.

R. C. Pattinson.


Surveyor to Lloyd's Register of Shipping

WEDNESDAY 24 MAY 1961

Date of Committer

Minute

DS 3 61 Subject (m)
TS 3 61



© 2021

Lloyd's Register
Foundation

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR.

SURVEY

Have the spaces now surveyed been cleared and cleaned as necessary?.....

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules?.....

Have the bilges been cleaned out and examined?..... Has cement in bottom been examined?.....

Has steelwork had rust removed and afterwards been recoated as necessary?.....

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork?

Has a Load Line Survey been held? No If so, state which

Have the shell and deck plating been drilled as per Rule?..... If so, Report 8(Dr) to be attached

Have any alterations to the approved scantlings and arrangements now been effected?..... If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes, or All—Yes.

The present condition of the following parts in so far as examined is to be reported:

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? ----- See Below

REMARKS, REPAIRS, Etc. (Contd.)

© 2021

Second Surveyor's Fee (if any)

Date when A/c. Rendered

17.0

Date when A/c. Rendered 5.4.61

© 2021

Surveyor's Fee (if any)
 When A/c. Rendered 5.4.61.