

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
                          Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

Your Ref: 042-01

8th October, 1964

C  
AH/RW

Dear Sirs,

m.s. "CINDERELLA"

I acknowledge receipt of your letter of the 29th September and regret that incorrect information was given to you in relation to the screwshaft data of this ship.

The case has now been further investigated in the light of the recent report which has been received from the Society's Surveyors at Rotterdam and it would appear that the shaft history is as follows:-

The shaft originally fitted in 1933 was marked BC 1438 JDS 20.10.33 and this was the working shaft until August, 1953.

In August, 1953, a new spare shaft was fitted marked C 184 BCF 153 RS 12.7.33.

In January, 1958, a new bronze continuous liner was fitted to the shaft marked C 184 BCF 153 RS 12.7.33 which was replaced by original working shaft and placed on board as spare.

In September, 1964, the original working shaft was replaced by the spare shaft which had been placed on board in January, 1958.

Yours faithfully,

Deputy Clerk to the  
Classification Committee

Messrs. S.A. Enchimar,  
30, Boulevard du Regent,  
Brussels,  
Belgium

© 2021

Lloyd's Register  
Foundation

011433-011440-0114