

Shaft now fitted was
first fitted 8.53 and

removed 1.58 on account of
fractured lines (new lines fitted)
& replace on beam as
opure until 9.64

Shaft removed at
that date in
approx

removed 8.53

refitted
working until 9.64

*

© 2021

1.58

Lloyd's Register
Foundation