



LLOYD'S REGISTER OF SHIPPING

2, "Danby Lodge", Lincombe Drive, Torquay

Telephone & Telegrams: Torquay 4193

12th February, 1959.

Reference

Dear Sir,

" OAK HILL "

With reference to my report No.8666 on the above vessel I find that I omitted to include the examination of the Main and Auxiliary Condensers and the Pumping Arrangements which were carried out by me during the survey now reported. The Auxiliary Condenser doors are somewhat wasted and require renewal.

Will you kindly enter same on my report or return the report to me for amendment, and please also attach the amended interim certificate, together with the copy of the interim certificate for the Hull which was not attached to the Rpt.8.

Yours faithfully,

24/6/59
The Secretary,
LONDON.

2021
Lloyd's Register
Foundation

011485-011492-0023

ER

CLASSIFICATION

H km

R.4

16/2/59

© 2021



Lloyd's Register
Foundation