

11.3 MAR 1959

4E

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

OAK HILL

REPORT

No.

Lorquay ltr 12/2/59.

The Int. Cert. sent with the above letter contains a condition of class concerning the doors of the auxiliary condenser, stated in the letter to require a wall. The Int. Cert., therefore, should be returned for inclusion of the Surveyors recommendation regarding these doors. Rpt 9. (No. 8666) should also be returned for necessary additions

R

16/2/59.



© 2021

Lloyd's Register  
Foundation