

Ship's name

R-140

Port

R0 28 JUL 1964

No.

58626

Class is subject to

NIL

Last survey date

27.6.64

Docking. Weardoun before 6.27m
after 17m

Screwshaft retained

Repairs due to steel wire catching on propeller. Also
water retaining bolts of after stern bush were missing &
bush was slack. Stern bush renewed. Screwshaft
examined & crack detected & crack found at top of
keyway P&S sides. Used spare shaft (crack detected)
fitted.

It is submitted that this
vessel is eligible for THE
RECORD T.S.C.L. 6.64 now

R.T.A. 24/64
64

© 2021
Lloyd's Register
Foundation