

COPY

Ship's name

SAN ANTONIO

Port

B. As

No.

35257

Last survey date

12/6/63

Class is subject to

Unscheduled repairs (8/54) to port diesel engine
bedplate installation being re-examined by 9/60.

No classification Survey.

Docking Wears down 1-02

T3 } main held.
ABS }
SPS }
ES }

S.R.L. item examined found satisfactory and to be
deleted from the list and a note made
in the appendix.

Repairs effected to main and auxiliary machinery
a number of electric cables renewed.

It is submitted that this
vessel is eligible for THE
RECORD.


Without subject

T3 (OG) } 6/63
ABS }
SPS }
ES }

50/8/63

S.R.L. - Appendix Note

Port diesel aux engine bedplate installation
unscheduled repairs



© 2021

Lloyd's Register

011579-011585-0016