

"VATNAJOKULL"

IT IS SUBMITTED a copy of the Owners' letter and the statement by Johan Ronning be forwarded to the Stockholm Surveyors for their comment.

They might also be informed it is stated by the Electrical Engineer Surveyor at Hull that he has surveyed the electrical installation and reports that the original cables were of pyrotenax and the ends had not been properly sealed off in the special manner required for cables of this type.

In this connection the Stockholm Surveyors should be referred to Circular No. 1801 which deals with the special precautions and procedure necessary for this type of cable and they should state whether these were carried out to their satisfaction.

~~It is understood the Owners have decided to completely strip out the pyrotenax wiring throughout the ship and to replace it with ordinary type of cable.~~

IT IS FURTHER SUBMITTED the Hull Surveyors be informed their remarks are noted and that the matter is being referred to the Stockholm Surveyors.

Write Skins
" Hull

EWJ.

15.1.48.



© 2021

Lloyd's Register
Foundation

011603 - 011609 - 0055