

26th May, 1961.

ANKIRK.

36 - As recommended.

37. "SENEGAL" - As recommended.

Please let me know which auxiliary air receiver was examined by you, and state its position in the engine room, as two of these units are fitted on board.

"PAUL GETTY". With reference to my letter of the 22nd February, I shall be pleased to receive without further delay your confirmation that the anchors and chain cables were tested under the supervision of the Society's Surveyors for assignment under the notation "LACP". Please also confirm that there are only 4 transverse bulk heads, and not 16 as reported.



© 2021

Lloyd's Register
Foundation

011610-011618-0047