

"TIO PEPE"

This case is stated in endorsement of 3. 3. 50.

The Bilbao Surveyors have stated in their letter of 10th instant that a 2" branch bilge suction has been fitted in the engine room, but the Cadiz Surveyor in his letter of the 17th instant states this item has not yet been fitted.

The Cadiz Surveyor also states the various oil fuel valves have not yet been made controllable from deck, as required by the Rules.

The electrical fuses are stated to be of an approved type.

IT IS SUBMITTED a copy of Cadiz letter of 17th instant be sent to Bilbao, and they be asked for their comments regarding the 2" bilge suction.



© 2021

Ent

Lloyd's Register
23. 3. 50.
Foundation

011610-011618-0167