

30th May, 1961.

AEUS.

4, - As recommended.

B961, - As recommended.

2, "PANTANASSA" ex "CANUK PORT" - As recommended, except that
is considered that the water end of the main condenser should
re-examined or renewed at the next drydocking, and I shall be
if you will issue an amended Interim Certificate accordingly.



© 2021

Lloyd's Register
Foundation

011636-011645-0188