

Ship's name

"BEECH HILL"

Port

Hna.

No. 2053

22 JAN 1963

Last survey date 30.11.62.

GB

Class is subject to set in shell plates Nos. 3 in 2nd and 3rd strakes below sheer (s.s.f) also to indented shell plates F.6, G.4 & 5, H.5 etc.(p.s.f) and to inner bottom plating in No.5 hold also to forward bulkhead of No.5 hold (s.s.) (holed) being examined and dealt with as necessary at the next drydocking.

S.R.L. Appendix (as before ~~xxxxxxx~~)

Nature of present survey (afloat and in drydock)

Docking: Contact damage - temporary repairs.

Recommendation

SUBMITTED record of 'DS 11,62' be assigned, subject as above, also to indented shell plates G.8 and H.9 (p.s.) being specially examined and dealt with as necessary by the Special Survey.

DS 11,62 Subject
IN S.R.L. APPENDIX.

Top of starboard hawse pipe E.W.

OFFICE NOTE

Bottom stiffened in Nos. 2,3,4,5 & 6

D.B.tanks - Hul.4,50.



© 2021

Lloyd's Register
Foundation

RSP X

27/12/62