

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

20 JUL 1959

4E

NAME..... M.V. "PACIFIC WIND"..... REPORT..... Vancouver No. 10607

Before this case receives consideration, the surveyor should be asked to refer to Vancouver Report No. 9336 and to state whether the condition of the Melitock repairs to No. 1 cylinder of the starboard forward auxiliary engine and bedplate of the starboard after auxiliary have been examined and dealt with. It is noted that the starboard forward auxiliary engine has been examined and found good and that the starboard main engine scavenge ~~pump~~ pump crosshead and guide have been previously renewed and not examined.

W.G.
7/7/59



© 2020

Lloyd's Register
Foundation

011757-011765-01176