

Ship's name

"MASTER ELIAS"

Port

Pir

29 JUL 10320
No.

Last survey date 10.6.63.

GB Class is subject to

indented bottom shell plates B.2 & 3,
C.3 & 4 (s.s.f) and B.3 & 4 and C.4 (p.s.f) being
specially examined and dealt with as necessary next
drydocking.

ACTION is DEFERRED for examination
in dry dock after grounding.

S.R.L. Appendix (as before ~~or xxxxxx~~)

Nature of present survey (afloat and in drydock)

Docking: Examination for possible damage due to grounding
- no structural damage found.

Recommendation

SUBMITTED record of 'DS 5,63' be assigned,
subject as above.

DS 5,63 Subject

IN S.R.L. APPENDIX.

Indents in shell plating 3rd
& 4th strakes below sheer (p & s).



© 2002
15/7/63

Lloyd's Register
Foundation

011826-011833-0059