

7- SEP 1962

Received from Chief Ship Surveyor.....

SHIP NAME "MASTER ELIAS" REPORT P.Sd. No. 7112

standing Conditions of Class: SUBJECT to indented bottom shell plates
B.2 & 3, C.3 & 4 (s.s.f) and B.3 & 4 and C.4 (p.s.f) being
specially examined and dealt with as necessary next drydocking.

Appendix. (As before ~~of 1961~~)

of Present Survey: (Afloat ~~and in dry dock~~)

Examination after grounding.

Recommendation:

SUBJECT as above, but ACTION be DEFERRED
for examination in dry dock after grounding.

SUBJECT

INSERT IN S.R.L.
Drydocking(grounding).

IN S.R.L. APPENDIX.
Indents in shell plating 3rd
& 4th strakes below sheer (p & s)



© 2021

Lloyd's Register
Foundation