

S.M. "SEASILVER"

Special survey type 1	due 7/1949
Load line certificate expires	30/ 7/1950
Annual load line survey	due 7/1949
Tailshaft	due 1/1951

ull 4/1947

Upper and lower shell plates in way of galley
bunkers port side sharply indented at lap and
several rivets in way started.

reat Yarmouth 1/1948

Port side from forward - B 5 slightly set up
between frames.

New tailshaft to be fitted at earliest opportunity.

ondon 8/1948

6 relief valves to be supplied and fitted at first
opportunity.

Reynolds chain drive to be renewed at first
convenient opportunity.



© 2021

Lloyd's Register
Foundation

611869-04876-0173