

20 MAY 1960 4E

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

'S NAME..... "AGOSTINO FASSIO"..... REPORT..... GEN..... No. 24998..

Docking. Screwshaft examined.

CS advanced.

ABS due 4.60. Now partly had.

Repairs effected to both water tube boilers. One 1¼" diameter steam generating tube found distorted and the tube ends plugged. Surveyor submits that this item be entered in the SRL Appendix to the effect that one 1¼" diameter steam generating tube has been plugged.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh record of TS (CL) 4.60 now, ABS (WT) 4.60 ~~now~~ and ABS (EX) 4.60 when the survey is completed.

ABS 4.60
now changed
JLB 4/10/60

To complete ABS (~~EX~~).

The safety valves of the exhaust gas auxiliary boiler to be adjusted under steam.

S.R.L. - Appendix Note

"One 1¼" diameter steam generating tube has been plugged" (Starbldr)

[Signature]

18.5.60.



© 2021 *Amend dr to Abs B*
Lloyd's Register
Foundation

011931-081935-0093