

18 AUG 1960

Received from Chief Ship Surveyor.....

"TRAUM"

REPORT

Bgn.

No. 4728

Conditions of Class:

SUBJECT to set in stem and indented shell plates B.2 & C.3 etc.(p.s.) being specially examined and dealt with by the Special Survey and to steering stand messenger and worn chain cable in way being renewed also to efficient sounding arrangements being fitted to Nos. 1 & 3 D.B.tanks at the earliest opportunity.

Appendix. (As before ~~or None~~)

Due: SPECIAL SURVEY (C) due 9,60.

Place of Present Survey: (Afloat and in dry dock)

Docking: Commencement of Special Survey:  
Permanent and deferred repairs to damage - cause not stated including part deferred items as above.

Special Features:

Interim Certificate in order (Yes-~~No~~-None)

~~Outstanding: (If any for S.S.)~~

FOR PORTION OF SURVEY HELD:- See this report.

to be completed by:

Recommendation:

SUBMITTED record of 'DS 4,60' be assigned, subject to efficient sounding arrangements being fitted to Nos. 1 & 3 D.B.tanks at the earliest opportunity and to set in and indented shell plates B.1 & 6 (s.s.), A.1, B.2 and C.2 (p.s.) being specially examined and dealt with as necessary by completion of the Special Survey, but without other conditions.

DS 4,60 Subject  
Without.

IN S.R.L. APPENDIX.  
Indents in forecastle side plating.

S.S. PART HELD.



© 2021

Lloyd's Register  
Foundation

*Handwritten:* 28/7/60