

011995-012002-0152

6m,9,61

Class is subject to

4E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

15 MAR 1962

SHIP'S NAME LEONIDAS CAMBANIS REPORT VCR RPT 8 No. 11391

Docking

Windlass inboard bearing pedestal found fractured,
temporary repairs effected and the Surveyor recommends
the windlass port inboard bearing pedestal be specially
examined and dealt with as necessary before the end of
December 1962.

It is submitted that this
vessel is to remain
CLASSED.

Subject as recommended

SEP 20 53584 (APR 62)

© 2020

Lloyd's Register
Foundation

15/3/62