

21 OCT 1965

SL Ship's name "GOODWORKER" Port BAHRAIN No. 1407

The Notation of drydocking overdue - class suspended 4,64 was inserted in the Register Book 17.4.64. Prior to class being suspended, indented sheerstrake plating etc (s.s) in way of Engine Room and bucket well plating (s.s) required to be specially examined and dealt with as necessary next drydocking.

The BAHRAIN Surveyors report 9,65 ship examined afloat on account of damage stated caused by contact. Side shell plating in way of boiler room (p & s) indented and temporary repairs effected. Permanent repairs recommended as necessary next drydocking.

IT IS SUBMITTED no further ACTION need be taken mean time.

*S.P.C.*  
20.10.65



© 2021

Lloyd's Register  
Foundation