

Rpt. 8

Port Fremantle. W.A.

No. 2053.

Date of writing Report 6th April '60.

When handed in at Local Office 6th April '60. Received London

Survey held at Albany. W.A.

No. of Visits 2

First Date 8-3-1960.

Last Date 30-3-1960.

12 APR 1960

## REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

18235

on the Iron or Steel M.S.

S.S.

"KOS VII"

Tons gross 1929.

Year

Month

Built at Mdb.

By Whom Smith's Dock Co. Ltd.

When

1929.

7.

Owners Cheynes Beach Whaling Co. Pty. Ltd.

Owner's address  
(If not already in R.B.)

Managers

Port of Registry

Brisbane.

Surveyed Afloat or in Drydock

Afloat.

Name of Dock

Date of last examn. in Drydock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 1943.  
To be filled in at Head Office.

Port

Fal.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr.). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined. Freeboard as marked on ship and now verified ft. ins.

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR

COMPLETION OF SPECIAL SURVEY AND LOAD LINE RENEWAL.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? Yes.  
If so, is the Report sent now, or when will it be sent? Now.

Is Classification Certificate required? If so, to be sent to Yes. Owners.  
Has Interim Certificate been issued? Yes.

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this Survey, for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. 1,55".

This vessel so far as now seen is in good condition fit to remain as classed and have notation S.S. 1,55 in the Register Book.

F. K. L. Birk.

(Sgd.) F. K. L. Birk.  
Surveyor to Lloyd's Register of Shipping

Date of Committee


Minute

MONDAY - 9 MAY 1960

SS 9 59  
MBS 3.60

ES 4.59

CERTIFICATE WRITTEN



© 2021

Lloyd's Register  
Foundation

012203-012210-0117



PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR COMPLETION OF SPECIAL SURVEY AND LOAD LINE BENEFIT SURVEY

Have the spaces now surveyed been cleared and cleaned as necessary? Yes.

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules?

Have the bilges been cleaned out and examined?

Has steelwork had rust removed and afterwards been recoated as necessary? Yes. Has cement in bottom been examined?

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork?

Has a Load Line Survey been held? Yes. If so, state which Renewal.

Have the shell and deck plating been drilled as per Rule? If so, Report 8 (Dr) to be attached.

Have any alterations to the approved scantlings and arrangements now been effected? If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3 or All—Yes.

The present condition of the following parts in so far as examined is to be reported:-

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? See Below

© 2021

Date when A/c. Rendered 6th April '60