

The class is subject to the starboard boiler now being used until its superheat drum has been repaired.

5 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "TAROONA"

REPORT Mel.

No. 12113

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

^aThe endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

~~DAMAGE &~~ WEAR AND TEAR.

Temporary repairs effected to superheater drum of starboard boiler, and the Surveyor recommends that the temporary repairs to the superheater drum of the starboard boiler be examined by the end of 12.52 and that the repaired superheater drum be renewed at the earliest opportunity. (See also endorsement dated 18.12.52)

It is submitted the vessel is eligible to remain as classed, with
~~record of Survey~~ subject now as recommended.



© 2021

Lloyd's Register
Foundation

012265-012272-0059

6.1.53.