



Lloyd's Register of Shipping.

95, Bothwell Street, Glasgow, C.2.

2nd February, 1935.

Dear Sir,

ference

With reference to the Glasgow First Entry Report No. 55344 on the T.S.S. "TAROONA", I beg to state that I included the rudder in list of items which had been electrically welded. This would have been more accurately described as "partially electrically welded".

In view of the topsides plating of this vessel being of Special Quality Steel, a notation of "Topsides - Special Quality Steel" should be made in the Register Book.

In the case of the S.S. "WAITAKI", Glasgow Report No. 54392, the rudder was completely electrically welded and it would appear that if such rudders are to have a notation in the Register Book, a recommendation to that effect should have been embodied in the report.

I am, Dear Sir,

Yours faithfully,

A.W. Paterson

The Secretary,

GLASGOW.



© 2021

Lloyd's Register
Foundation

012265-012272-0050