

15504

GB

LOCAL (Classification Contemplated)
"Examined 4.48.

Chief Surveyors

Received from Chief Surveyors

L'S NAME "MARABANK" Report Gal. No. 5042

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/02.)

PERIODICAL No. SPECIAL SURVEY PARTLY HELD. Adl. & Syd. 4.48 Lon 8.48
(For Classification) When proposed to be completed Brs. 9.48 Advancement of S.S. Docking.

COMPLETE S.S.
of Survey held, &c..

Testing of O.F. settling tanks, deep tanks, F.W. tanks, in 'tween decks.
Examination of E & B spaces, steering gear, windlass, decks, general equipment, F.W. tanks in 'tween decks.
Verification of freeboard.
Striking plates to fit under sounding pipes in No. 5. hold.
(Furnishing of F.E. report in accordance with Circular No. 1871.)

NOTED.

Indented sheerstrake plate No. 2. (s.s.) required to be permanently repaired at the first convenient opportunity.

ACTION is DEFERRED for completion of SPECIAL SURVEY.

A considerable part of the SPECIAL SURVEY requirements has been complied with at this time, and the Surveyors should be requested to furnish a F.E. report in accordance with Circular No. 1871.

Gal.
London Surveyors 8.48.
F.E. Rpt

ABM.
24.10.48
BTM



© 2021

Lloyd's Register
Foundation

012306-012314-0123