

012315-012323-0229

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel S.S. "WAR BRAHMIN" Report Grk No. 17609

## For the CHIEF SHIP SURVEYOR \_\_\_\_\_

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

The Downton Pump has been dispensed with for the present.

✗ 100 A.1. (steel) "Carrying Petroleum in Bulk"  
 1 Dk (steel). 2 (w) beams, & Webframes. Longitudinal framing.

Cell DB UEYB 72' 250t. 450' 65t. FPT 95t. APT 75t.

FK. 15 BH. pk.cem. Lloyd's A/C.P. P 50', B 121', F 39'.

"Middle line bulkhead not oiltight."

© 2021

Lloyd's Register  
Foundation

19-2-20