

Received from Chief Ship Surveyor..... 18 FEB 1959

NAME "ESSO FLANDRE" REPORT Msl. No. 12520.

Standing Conditions of Class: Subject to set up keel plating being re-examined next drydocking, and to pitted bottom shell plating (internally) in way of Nos. 3, 5 & 7 centre tanks and No. 6 (p.s) and No. 7 (s.s) cargo wing tanks being kept under observation and reported at each drydocking.

Assessment of Certificate (~~As before~~ or None)

Place of Present Survey: (~~At float and in dry dock~~)

Docking; Minor W & T repairs; Permanent repairs to damage (H.W.) involving fractured shell plates (p.s) in way of No. 7 cargo tank; Examination of subject items, as above.

Recommendation: SUBMITTED record of 'DS 1,59' be assigned as recommended, SUBJECT as above.

DS 1,59. Subject.

ENGINEER SURVEYOR ~~X~~ to note.
note

lk(new)



012346-012357-0232

© 2021

J. H. 25/59
Lloyd's Register
Foundation