


24 OCT 1957

Received from Chief Engineer Surveyor .....

REPORT.....Kob.....No. 4975.

Docking. Screwshaft seen. Spare screwshaft now fitted.

RECORD,



© 2021

Lloyd's Register  
Foundation

012377-012385-0352