

14 AUG 1957<sup>4E</sup>

by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

NAME..... BARAU..... REPORT..... Sba..... No. 6125.....

ES due 9.57, now held.

Docking.

The main engine attached sea water cooling and bilge pump bodies found ~~wasted~~, now temporarily repaired and tested, found tight, and the Surveyors recommend the main engine attached sea water cooling and bilge pump bodies be renewed before or at the next drydocking. It is stated that new pumps have now been ordered.

IT IS SUBMITTED this vessel is eligible for the record ES 7.57, subject as recommended.



© 2021

6024

6.8.57.

Lloyd's Register  
Foundation

012431-012438-0387