

Received from Chief Ship Surveyor

SHIP'S NAME "DONAI"

REPORT Hav. No. 9773

Standing Conditions of Class: Subject to indented shell plate G.10 (s.s.) being dealt with by next Special Survey, to bottom shell plating (p.s.a.) and side shell plating, etc. in way of No.8 tank (p.s.) being permanently repaired next drydocking, and to the supply and verification of 15 fathoms of chain cable as soon as possible.

Improvement of Class (B) ~~As before~~ or None

Place of Present Survey: (Afloat and in dry dock)

Docking: Wear and tear repairs and to part of the deferred items as above: Alterations to midship deep tanks in accordance with approved amended plans: Equipment (verification of 15 fathoms of c.c. as above).

Recommendation:

SUBMITTED record of docking 11,56 be assigned, subject to indented shell plate G.10 (s.s.) being dealt with next Special Survey, and to side shell plating, etc. in way of No.8 tank being permanently repaired next drydocking, but without other conditions.

11,56 Hav. Subject
Without.

SHIP PLANS DEPT. TO NOTE ALTERATIONS.

Blk(new)

012646-012655-0131



© 2281
17-1-57

Lloyd's Register
Foundation