

2- JUL 1962

Received from Chief Ship Surveyor.....

"INCHCASTLE"

REPORT KOB.

No. 10551

Conditions of Class: SUBJECT to damaged shell plate in 4th strake
w/ sheerstrake in way of No.4 hold (s.s), set down upper deck plating
Internals in way of No.5 hold, ventilators (p.s) and to No.5 D.B.
Air pipe (p.s) being examined and dealt with as necessary on ship's
arrival at Osaka from present voyage.

ix. (As before ~~xxxxxxx~~)

Present Survey: (Afloat ~~xxxxxxxxxxxx~~)

Damage repairs (heavy weather) and to part
of the deferred items as above.

on: SUBMITTED the ship is eligible to remain as classed,
subject to shell plate in 4th below sheer (s.s.) in
way of No.4 hold (part doubled) being examined and
dealt with as necessary next drydocking, without
other conditions!

w Subject
amended
without.

012663-012668-0125

© 2021
Lloyd's Register
Foundation

S.P.R.
1.4.4.