

Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRS

Received London

3 DEC 1962

Ship's Name ~~XXXXX~~ T.S. TANKER "HERNANDARIAS" Gross tons 1752

Is there a rpt. 9? Yes

Port BUENOS AIRES Rpt. No. 34519

No. of visits One

First date and

Last date 15-11-62

Interim Cert. issued
& copy herewith? Yes

Damage rpt. issued
& copy herewith? No

Last rpt. (H.Q. only)

Date of
completing rpt. 22-11-62

Surveyed at, if different from Port above -

Surveyed afloat
and/or in D.D. Drydock

Last date of examination in D.D. 15-11-62

Has a Load Line
Survey been held? No

Freeboard Marks verified No

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig) (PS)

Survey fees

\$ 3,000.00

Damage fee

Nil

Expenses

\$ 200.00

S.A. fee Nil

I have surveyed the above ship in accordance with the Rules for Docking

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

I recommend that this ship remain as classed with ~~XXXXXX~~ fresh record of dry docking 11, 62

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

R.M. Leach

Surveyor to Lloyd's Register of Shipping

Date of Committee

WEDNESDAY - 2 JAN 1963

Minute

DS 11. 62

Port TS 11. 62.

Write BX (m)

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register
Foundation

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC. The reason for repairs must be stated and repairs on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs and, besides being detailed above, should be noted in the following summary. *State what action has been taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new.* Any alterations in existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed					
Removed and faired or replaced					
Faired or repaired in place					
		N O N E			

Rpt. 8 (P.S.) TANKER

Ship's Name ~~XXXXXX~~ T.S. TANKER "HERNANDARIAS"

S.S. () Due 4, 65

Port BUENOS AIRES Rpt. No. 34519

Examined & condition		Examined & condition	
In dry dock from	14-11-62	* Hatchways	Good
" " " to	15-11-62	* Ventilators	Good
Shell plating	Good	* Air & sounding pipes	Good
Sternframe	Good	Doublers under sounding pipes	Not examined
Rudder	Good	Steering arrangements (main)	Good
Was rudder lifted?	No	" " (aux)	Good
Plating, etc. in way of shell openings	None	Windlass	Good
Side scuttles & deadlights	Good	Masts & rigging	Good
Overbd. scuppers & discharges	Good	Hand pumps & suction	Not examined
Hold	Not examined	W.T. doors	None
F.P. spaces	Not examined	Bulwarks, freeing ports, etc.	Good
Chain locker	Not examined	Summer freeboard as verified	Not verified
A.P. spaces	Not examined	EQUIPMENT:	
Engine space	Not examined	Equipment letter	
Boiler space	Not examined	Anchors: No. on board	
Under E. & B.	Not examined	Cables { State if ranged Length on board Mean dia. range from Rule length	
Coal bunker	None		
Tunnel & well	Not examined		
Cement, asphalt, etc., on btm. shell	Not examined		
Weather decks	Good	Mooring ropes	Sufficient
* Casings	Good	Other items:	
* Deckhouses	Good		
* Superstructures	Good		
* Skylights	Good		
* Companionways	Good		

COMPLETE

STATED

EXAMINED & CONDITION		TANKS	TESTED & CONDITION	
PORT	STARBOARD		PORT	STARBOARD
		F.P. Tank		
		A.P. Tank		
		Deep Tank No. 1		
		" " No. 2		

For other tanks see overleaf

* These items to include their closing appliances
Where a part Special Survey and, say, dry docking Survey are held at the same time, the items for SS should be marked "For SS".

R.M. Leach

Surveyor to Lloyd's Register of Shipping

Lloyd's Register Foundation