

5th July, 1960.

DISCLOSED
BEHIND
No 1139

DJAKARTA


5751 - As recommended.

5755 "BENGAWAN" - As recommended. You should state the defect in the auxiliary FW cooler overboard discharge valve cover as in the report the sea connections are stated to be "good". Furthermore you should in future report such defects in the appropriate space in the Rpt.9 as well as marking the defective items with a "†".

"TANDJUNG DATU")
"TANDJUNG TORAWITAN") I acknowledge receipt of your letter
"TANDJUNG HAYA") of the 24th June, the contents of which
previously assigned in the cases of the "TANDJUNG" TORAWITAN" and have been noted. The notations of ABS 7.59
"TANDJUNG HAYA" have now been deleted by the Committee.

In all three cases the following note has been inserted in the SRL Appendix

"auxiliary boiler not in service and not to be used until surveyed, safety valves adjusted and accumulation test held."



© 2021

Lloyd's Register
Foundation

013008-013017-0030