

S.S. "PINNACLES"
Baltimore Report No. 11651

List of repairs recommended at Baltimore
in April 1959.

SHELL PLATES NUMBERED FROM FORWARD.

Keel plates Nos. 3, 6, 7, 8, 9, 10, 11, 12, 12 $\frac{1}{2}$, 13, 14 and 15 to be renewed.
Starboard side "A" strake shell plates Nos. 6, 7, 8, 9, 10, 11, 12, 13, 14 and 15 to be renewed.

Starboard side "B" strake shell plates Nos. 8, 9, 10, 11, 12, 13, 14 and 15 to be renewed.

Starboard side "C" strake shell plates Nos. 7, 8, 9, 10, 11, 12 and 15 to be renewed.

Starboard side "D" strake shell plates Nos. 6, 7, 8, 9, and 10 to be renewed.

Port side "A" strake shell plates Nos. 8, 9, 10, 11, 12, 13, 14 and 15 to be renewed.

Port Side "B" strake shell plates Nos. 7, 7 $\frac{1}{2}$, 8, 9, 10, 11, 12, 13, 14 and 15 to be renewed.

Port side "C" strake shell plates Nos. 8, 9, 10, 11, 12, 13 and 14 to be renewed.

Port side "D" strake shell plates Nos. 6, 7, 8, 9 and 10 to be renewed.

NOTE: -

The survey was carried out generally by the Owners to estimate the cost of repairs for the next Special Survey. It is understood that a re-examination of the vessel throughout would be necessary prior to the above repairs being carried out.



© 2021

Lloyd's Register
Foundation

013033-013041-0097

SR

CLASSIFICATION

H
u/s.
MMI

13-3-EB

Await report

18
2-18-99



© 2021

Lloyd's Register
Foundation