

COPY.

REC'D NEW YORK MAR 16 1959

Lloyd's Register of Shipping.



Miami, Florida

Port
March 10, 1959

Mooring Ropes.

This is to Certify that

FRED H. HALLBAUER

the undersigned Surveyor to this Society did at the request of Port Everglades Terminal Company, Agents, Port Everglades, Fla., attend and survey the S/S "PINNACLES", while the vessel lay afloat at her discharging berth, Port Everglades, Fla., on March 10, 1959, with regard to the general condition of mooring lines.

It was stated that while loading her present cargo at Lake Maracaibo, Venezuela, the vessel was moored to four mooring buoys plus having starboard anchor on bottom, and that the lines presented to the undersigned surveyor for examination were the same lines used at that time.

UPON EXAMINATION FOUND:

Four lines on forecastle head, all considered to be of ample length for this vessel:

One 9" circumference manila rope, considered nearly new and in good condition.

One 9" circumference manila rope, considered nearly new and in good condition.

One 9" circumference manila rope, showed some indications of minor wear and is considered satisfactory and serviceable.

One 8" circumference manila rope, new.


Five lines on poop deck, all considered to be of ample length, were examined as follows:

One 9" circumference manila rope, showed some indications of minor wear and considered satisfactory and serviceable.

One 9" circumference manila rope, showed some indications of minor wear and considered satisfactory and serviceable.

No. 243

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Page 2.


No. 243

One 8" circumference manila rope, showed some indications of minor wear and considered satisfactory and serviceable.

One 8" circumference manila rope, showed evidence of considerable use but considered serviceable.

One 8" circumference manila rope, showed evidence of considerable use but considered serviceable.

Signed without prejudice.



Fred H. Hallbauer
Surveyor



© 2021

Lloyd's Register
Foundation

0104 2/2