

T. 2. Tanker.

Sent to Chief Surveyors.....

Received from Chief Surveyors.

SHIP'S NAME

Pinnacles.

REPORT

Bal.

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the repairs, so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/54)

Nature of Survey

Docking & fitting of docking  
brackets. When due.....

Has a Sur

Subject to sternframe (EW reinforced 5:54)  
being specially examined next drydocking.

Office note

Docking brackets fitted Bal 5:54.

Had this case been dealt with in  
this office the repairs to sternframe would  
have been made a condition of Class to  
be specially examined next drydocking.

SPK.  
20-7-54

✓ and  
Records Dept.  
to note.

Fractured sternframe  
Docking brackets fitted.

Register  
Foundation

013033-013041-0114